R262411

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER SECTION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 2016 PA 407, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 2016 PA 407 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

LOCATION

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

MANUFACTURER: Raypak
BOILER TYPE: Water Tube
YEAR BUILT: 2001
MAX OPR PRESS: 60
SV PRESS: 60
INSPECTOR: Daniel Kyle Hundley

STATE NO: MIR398827
NB# / MFG#: 185765
DATE INSP: 11/13/2024
EXP DATE: 11/13/2027

ORLENE HAWKS
DIRECTOR

David Stenrose
Chief, Boiler Section

PLACE IN BOILER ROOM

BCC-300 (Rev. 1/14)

R262409

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER SECTION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 2016 PA 407, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 2016 PA 407 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

LOCATION

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

MANUFACTURER: Raypak
BOILER TYPE: Water Tube
YEAR BUILT: 2001
MAX OPR PRESS: 60
SV PRESS: 60
INSPECTOR: Daniel Kyle Hundley

STATE NO: MIR398825
NB# / MFG#: 185766
DATE INSP: 11/13/2024
EXP DATE: 11/13/2027

ORLENE HAWKS
DIRECTOR

David Stenrose
Chief, Boiler Section

BCC-300 (Rev. 1/14)

PLACE IN BOILER ROOM

R262410

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER SECTION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 2016 PA 407, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 2016 PA 407 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

LOCATION

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

MANUFACTURER: Raypak
BOILER TYPE: Water Tube
YEAR BUILT: 2001
MAX OPR PRESS: 60
SV PRESS: 60
INSPECTOR: Daniel Kyle Hundley

STATE NO: MIR398826
NB# / MFG#: 185764
DATE INSP: 11/13/2024
EXP DATE: 11/13/2027

ORLENE HAWKS
DIRECTOR

David Stenrose
Chief, Boiler Section

PLACE IN BOILER ROOM

BCC-300 (Rev. 1/14)

R262408

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER SECTION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 2016 PA 407, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 2016 PA 407 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

LOCATION

New Branches Charter Academy
3662 Poinsettia Ave SE
Grand Rapids, MI 49508-5546

MANUFACTURER: Kewanee
BOILER TYPE: Fire Tube
YEAR BUILT: 1955
MAX OPR PRESS: 30
SV PRESS: 30
INSPECTOR: Daniel Kyle Hundley

STATE NO: MIR093520
NB# / MFG#: H6061
DATE INSP: 11/13/2024
EXP DATE: 11/13/2027

ORLENE HAWKS
DIRECTOR

David Stenrose
Chief, Boiler Section

BCC-300 (Rev. 1/14)

PLACE IN BOILER ROOM