

Kingsbury Country Day
 JAS
 Hazard Assessment

2/27/19

FS#	FS Description	Homogeneous Area Description	HA#	Amount	Units	S/TSI/M	Hazard Assessment	Response		
								Action	Justification	Schedule
1	Main Entrance	Fire Door	6	4 Total	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
5	Gym Storage/Electrical	Fire Door	6	3 Total	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
6	Kitchen	Fire Door	6	4 Total	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
10	Custodial Closet	Fire Door	6	1 Total	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
1	Main Entrance	Fire Door Frame	7	2 Total	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
2	Main Gym	Gym Wood Floor	8	6,750 Sq. Ft.	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
7	Stage	Gym Wood Floor	8	990 Sq. Ft.	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
2	Main Gym	Mastic for Gym Wood Floor	9	6,750 Sq. Ft.	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE
7	Stage	Mastic for Gym Wood Floor	9	990 Sq. Ft.	M	*Non-Friable	Maintain under O & M	Material is Intact	Ongoing	NO CHANGE